

Flow-Liner® presents a “Potable Water Solution with Neofit®”

Issue

East Newark Townhomes, a quaint apartment complex in Newark, Ohio, was in need of replacing their leaking copper water service pipe in a timely manner with minimal excavation. Their plumber contacted a Flow-Liner® Certified Neofit® Installer for a non-invasive option.

Solution

A Flow-Liner® Certified Neofit® Installer lined the existing 40 feet of 1-1/4 inch copper water service pipe with the Neofit® liner. Only one excavation pit was required outside the building. An existing access area inside the building, where the service pipe extended up through the concrete floor, was also utilized.

Results

The water service pipe, from city curb stop to the mechanical room, was tested and placed back in service the same day. The customer was very satisfied with the finished project:

“Neofit® pipe lining saved us from having to dig up and replace the water service piping, which would have been very costly and inconvenient. Neofit® is a viable option in comparison with pipe replacement.”



**“ALSO A GREAT OPTION
FOR LEAD PIPES”**



Only one minor excavation site



Neofit® Equipment



Neofit® Equipment Set-up next to building



Existing access through inside wall



Installation of Neofit® in existing water service pipe



Water service pipe after Neofit® was installed

We are pleased to announce another successful project and proudly add

East Newark Townhomes

to our list of happy and satisfied customers.